U.S. Senate Desk Description and Condition Report

Desk No: 66.00000.031

Paper Label No.(on shelf bottom): N/A Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 31, 31, XXXI / Top: 31 (stamped), 27 (crayon) / Drawer Bottom: outside - 31 (pencil) / Inside Case Back: Inside (pencil) / Inkwell: 31 (pencil)

Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 1/2	32		
Width (front)	27 7/8	26 3/4	25 3/4	
Width (rear)	27	26	25 1/16	
Depth	20 1/8	20 1/16	19 3/16	9 1/4

^{*} Note: Dimensions do not include "booster" blocks added to feet or writing top.

Woods

Primary:	Mahogany ■ Mahogany veneer ■	Character of case mahogany:	Plain 🗆
	Rosewood veneer		Ribbon
Other Wo	ood (specify):		Mottled □
-			Crotch □
			Other 🗆

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides			1		
Drawer Bottom			1		
Drawer Back			1		
Case Interior	1		1		
Drawer Front	1				

Desk Descripti	on and Conditi	on Repo	rt: Desk No:	031				Page 2
Construction	Details							
_eg:								
	Wood Type				rosewood crossband	other crossband	cross	
	mahog, vene	er						
	solid mahoga	ny					-	,
	other:							
Foot construct	ion:		1-part ■	Co	ckbead width on	bottom of d		nt:
			2-part □ 5-part □				Full	width
Double bead o	on edge of leg:	Other:	id: Thick 🗆	Ор	ening in original	top for inkw	rell:	Yes □
Shape of cros	s-stretcher edg	es:	kness: 1 "		11.00		Applied	boss I
			tangular		et distance of sir	igle bead o	n desk ba	ck
	1	1	11	pai	iei.		Sid	e: 1 1/4
Spindle type: Number	Thick 1	Thin 7	Other 2				Botto	Top: 1' om: 7/8'
Joinery of low	er drawer blade	e to case	sides:		GMU			
		single	dovetail	N	o. of Glue Block	s Case	Stretch'r	Shelf
		2 d	ovetails	-	Original/Old			2
		3 d	ovetails		New/Recent			
			lap joint		Missing			
	othe	er: joinery	y not visible	Inte	erior case-side fl	ush with co	rner block	? Yes [
Shelf molding	applied:		Yes 🗆		TT-			140
			No 🔳	Wi	dth of drawer-op	ening offset	t Rig	ht : 1/2

Condition of Desk

Structure

nts: Yes ■	Drawer bottom p	ieced-out a	at back edge	: Yes ■
No □				No 🗆
Yes	Wear on Feet	Extreme	Moderate	Minor
No 🗆	Front		/	
	Rear			1
Yes 🗆	Number of loose	spindles:		-
No ■				No: 2
Extreme □ Moderate ■		이 시간 경험하게 되었다.	es:	No: 3
Minor 🗆			s-banding:	Yes 🗆
Yes ■	(show on scher	matic)		No 🖩
Yes ■ Damaged ■			banding:	Yes ■
Missing		se veneers	&	Yes ■
Loose 🗆		matic)		No □
olacements 🗆	Shelf supports:		Origi	nal/old
Yes ■			New	recent
No □			N	Nissing 🗆
Yes ■	Spindle support	board in ca	ise:	Yes 🗆
No 🗆				No \blacksquare
	No Yes No Yes No Yes No No Xes Minor Yes Minor Yes Yes Ves No No Yes No Yes Yes Yes No Yes Yes No Yes No Yes No Yes No Yes No Yes No Yes Yes Yes Yes Yes Yes Yes Yes	Yes Wear on Feet Front Rear Yes Number of loose Number of repla (show on scher Minor Replaced venee (show on scher Yes Missing veneers (show on scher Yes Show on scher Shelf supports Yes Spindle support	Yes Wear on Feet Extreme Front Rear Yes Number of loose spindles: No Number of replaced spindle (show on schematic) Replaced veneers and cross (show on schematic) Yes Missing veneers and cross (show on schematic) Missing Delaminated/loose veneers cross-banding: (show on schematic) Delaminated/loose veneers cross-banding: (show on schematic) Shelf supports: Yes Missing Spindle support board in care	Yes ■

Finish

Age	Excellent	Good	Fair	Poor
New				
Old			1	
Unk.				

Note: Describe finish problems in narrative.

Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)	1		
Knob (R)			

Toe cap size:	Right toe:		
	Left toe:	2	